

# Safety Notice – 9/3/2024

## Bay Door Remote Placement on Apparatus



Here is an example of how a bay door remote could accidentally be pressed while placing a vehicle in drive.

- MCFRS has recently had two significant bay door strikes involving doors that did NOT have a timer.
- If there is no timer, the only way the door can come down is if the remote or wall switch were inadvertently pressed.
- To combat this, the Safety Section recommends that all bay door remotes be placed on the driver's visor to prevent interference with other switches/buttons/radios etc.
- If your remote is broken/missing a clip, please go through the proper channels to have it replaced.



Thank you for your time and attention in getting this done ASAP