******WARNING******

****

******WARNING******

Fire Sprinkler pipes are located under insulation

Use extreme caution when entering and working in attic

Do not step directly on pipe.

Any storage or flooring will compress the insulation and reduce its insulating qualities and effectivness.

After completing work, use care to assure that all insulation is returned to its proper place to prevent possible freezing of pipes.

******WARNING******

****