Resurfacing: Fire Stations (P458429)

Category
Sub Category
Administering Agency
Planning Area

Public Safety Fire/Rescue Service General Services (AAGE29) Countywide Date Last Modified 11/25/16
Required Adequate Public Facility No
Relocation Impact None
Status Ongoing

	Total	Thru FY16	Rem FY16	Total 6 Years	FY 17	FY 18	FY 19	FY 20	FY 21	FY 22	Beyond 6 Yrs
EXPENDITURE SCHEDULE (\$000s)											
Planning, Design and Supervision	753	249	0	504	84	84	84	84	84	84	0
Land	0	0	0	0	0	0	0	0	0	0	0
Site Improvements and Utilities	0	0	0	0	0	0	0	0	0	0	0
Construction	1,876	75	505	1,296	216	216	216	216	216	216	0
Other	0	0	0	0	0	0	0	0	0	0	0
Total	2,629	324	505	1,800	300	300	300	300	300	300	0
FUNDING SCHEDULE (\$000s)											
G.O. Bonds	2,629	324	505	1,800	300	300	300	300	300	300	0
Total	2,629	324	505	1,800	300	300	300	300	300	300	0

APPROPRIATION AND EXPENDITURE DATA (000s)

Appropriation Request	FY 18	300
Supplemental Appropriation Request	0	
Transfer	0	
Cumulative Appropriation		1,129
Expenditure / Encumbrances		557
Unencumbered Balance	•	572

Date First Appropriation	FY 84	
First Cost Estimate		
Current Scope	FY 17	2,629
Last FY's Cost Estimate		2,629

Description

This project provides for the repair and replacement of paved surfaces at fire and rescue stations where existing paved surfaces are in poor and deteriorating condition.

Estimated Schedule

Scheduling is determined through annual inspections performed by the Department of General Services, Division of Building Design and Construction, in consultation with the Montgomery County Fire and Rescue Service. The station schedule displays anticipated priorities only and may be amended, if required, due to fire station pavement safety considerations.

Cost Change

The increase is due to the addition of funding in FY21 and FY22, partially offset by capitalizing prior year expenditures.

Justification

The current candidate project list was determined by a survey conducted by the Department of General Services, Division of Building Design and Construction. The ongoing project need for exterior resurfacing at fire and rescue stations is due to the continuous use by heavy equipment such as pumpers and ladder trucks. While surfaces at some stations have lasted many years, others have deteriorated and failed in less than seven years.

Fiscal Note

Debt service for this project will be financed with Consolidated Fire Tax District Funds.

Disclosures

Expenditures will continue indefinitely.

Coordination

Montgomery County Fire and Rescue Service, Local Volunteer Fire and Rescue Departments, Department of General Services