# Guardrail Projects (P508113)

Category
Sub Category
Administering Agency
Planning Area

Transportation
Traffic Improvements
Transportation (AAGE30)
Countywide

Date Last Modified
Required Adequate Public Facility
Relocation Impact

Status

12/6/16 No None Ongoing

	Total	Thru FY16	Rem FY16	Total 6 Years	FY 17	FY 18	FY 19	FY 20	FY 21	FY 22	Beyond 6 Yrs
EXPENDITURE SCHEDULE (\$000s)											
Planning, Design and Supervision	569	84	11	474	79	79	79	79	79	79	0
Land	0	0	0	0	0	0	0	0	0	0	0
Site Improvements and Utilities	1,980	561	3	1,416	236	236	236	236	236	236	0
Construction	4	4	0	0	0	0	0	0	0	0	0
Other	0	0	0	0	0	0	0	0	0	0	0
Total	2,553	649	14	1,890	315	315	315	315	315	315	0
FUNDING SCHEDULE (\$000s)											
G.O. Bonds	2,553	649	14	1,890	315	315	315	315	315	315	0
Total	2,553	649	14	1,890	315	315	315	315	315	315	0

### APPROPRIATION AND EXPENDITURE DATA (000s)

Appropriation Request	FY 18	315
Supplemental Appropriation Request	t	0
Transfer		0
Cumulative Appropriation		978
Expenditure / Encumbrances		649
Unencumbered Balance		329

Date First Appropriation	FY 81	
First Cost Estimate		
Current Scope	FY 17	2,553
Last FY's Cost Estimate		2,553

## Description

This project provides for: 1) installation of guardrail where they are determined to be required; 2) upgrading identified deficient and/or non-compliant end treatments to meet current Maryland State Highway Administration (MSHA) standards; 3) establishment of a 25-year life-cycle replacement program; and 4) replacement of guardrail damaged beyond repair in crashes.

## **Cost Change**

Cost increase due to the addition of FY21-22 to this ongoing level-of-effort project partially offset by capitalization of prior year expenditures.

#### **Justification**

Guardrails reduce the severity of run-off-the-road accidents, prevent collisions with fixed objects and protect embankments. Damaged or missing guardrails and deficient end treatments present a hazard to motorists, cyclists, and pedestrians. Guardrails have a finite service life and must be replaced at the end of this service life or when damaged in order to continue to provide safety benefits for all users. The March 2010, Report of the Infrastructure Maintenance Task Force, confirmed this and identified the need for guardrail life-cycle replacement. The existing tapered and buried guardrail end treatments provide a ramp for errant vehicles and do not meet current MSHA standards. A study was completed to identify these substandard or deficient end treatments and to replace them to meet modern crash attenuation standards.

#### **Disclosures**

Expenditures will continue indefinitely.

#### Coordination

Federal Highway Administration, Maryland State Highway Administration, Montgomery County Public Schools