



Site Improvements: College

(P076601)

Category	Montgomery College	Date Last Modified	05/25/21
SubCategory	Higher Education	Administering Agency	Montgomery College
Planning Area	Countywide	Status	Ongoing

EXPENDITURE SCHEDULE (\$000s)

Cost Elements	Total	Thru FY20	Rem FY20	Total 6 Years	FY 21	FY 22	FY 23	FY 24	FY 25	FY 26	Beyond 6 Years
Planning, Design and Supervision	3,514	2,588	26	900	200	140	140	140	140	140	-
Site Improvements and Utilities	15,930	13,010	-	2,920	420	480	480	570	390	580	-
Construction	2,890	2,387	23	480	80	80	80	80	80	80	-
TOTAL EXPENDITURES	22,334	17,985	49	4,300	700	700	700	790	610	800	-

FUNDING SCHEDULE (\$000s)

Funding Source	Total	Thru FY20	Rem FY20	Total 6 Years	FY 21	FY 22	FY 23	FY 24	FY 25	FY 26	Beyond 6 Years
Current Revenue: General	1,000	1,000	-	-	-	-	-	-	-	-	-
G.O. Bonds	21,334	16,985	49	4,300	700	700	700	790	610	800	-
TOTAL FUNDING SOURCES	22,334	17,985	49	4,300	700	700	700	790	610	800	-

APPROPRIATION AND EXPENDITURE DATA (\$000s)

Appropriation FY 22 Request	700	Year First Appropriation	FY07
Cumulative Appropriation	18,734	Last FY's Cost Estimate	22,634
Expenditure / Encumbrances	18,034		
Unencumbered Balance	700		

PROJECT DESCRIPTION

This project funds the repair, maintenance and improvements of the College's site infrastructure. This may include, but is not limited to: roadways, parking lots, walkways, site lighting, external site signage and site communications infrastructure. The Stormwater Management project, #076602, was added to the scope of this project in FY2009. This project also provides for the rehabilitation and structural maintenance of storm water management facilities on the College's campuses. This includes, but is not limited to: dam or spillway repairs, pond dredging, storm drain system repairs/replacement, and storm water management studies to determine best practice solutions. This project also funds the repair, maintenance and improvement of the College's outdoor athletic facilities. This may include, but is not limited to: athletic field lighting, reconfiguration and upgrade; the repair/replacement of bleachers; turf renovation including regrading, sodding and irrigation/drainage management; repair/replacement of running tracks and tennis courts; and the repair/replacement of backstops, player protection fencing and benches. ** Note: In FY11, the Outdoor Athletics Facilities: College project (CIP No. 076600) was merged into this project.

LOCATION

College-wide

COST CHANGE

Spending reductions in FY24 and FY25 due to affordability.

PROJECT JUSTIFICATION

In December 2004, the County Council initiated an Infrastructure Maintenance Task Force which gathered information on the maintenance needs of County agencies. The first objective was to identify the direst needs of agencies for additional funding; while the long-term goal was to initiate an ongoing, regular process to update and improve the inventory and analysis of infrastructure maintenance needs. As the College had already completed a facilities assessment, adequate information was available for buildings and a process was already underway to address these needs. However, less attention had been given to site issues. An outcome of this task force was to create projects to address these site needs. Related studies include the Montgomery College 2020 Strategic Plan, Collegewide Facilities Condition Assessment Update (12/13), the Collegewide Master Plan 2013-2023 (2/16), and the County Council Report of the Infrastructure Maintenance Task Force (3/16).

OTHER

FY21 Appropriation: \$700,000 (G.O. Bonds). FY22 Appropriation: \$700,000 (G.O. Bonds). The following fund transfer has been made to this project: \$1,400,000 from the Science East Building renovation (P076623)(BOT Resol. #: 15-09-77, 9/21/15).

DISCLOSURES

Expenditures will continue indefinitely.

COORDINATION

This project is coordinated with Utility Master Plans and building renovations on the Rockville, Germantown, and Takoma Park Silver Spring Campuses., Capital Renewal: College (CIP No. P096600), Elevator Modernization: College (CIP No. P056608)