## SCHOOL-RELATED CRASH INFRASTRUCTURE REVIEW

## MONTGOMERY COUNTY DEPARTMENT OF TRANSPORTATION (MCDOT)

• Location: Montgomery Village Ave at Hob Hill Way Intersection

Crash Date: 04/23/2025Crash Time: 07:35 AM

School Name: Watkins Mill High SchoolSchool Walkshed Boundary (Inside): Yes

Local Case No: 250017560Review Date:8/11/2025

## **DESCRIPTION OF INCIDENT AND CRASH DETAIL**

On Wednesday, April 23, 2025, at approximately 7:35 AM, a pedestrian was struck while in the crosswalk on the north leg of Montgomery Village Avenue. The motorist was making a left turn from Apple Ridge Road onto Montgomery Village Avenue when the collision occurred. The crash report indicated that the incident took place within a marked crosswalk. The pedestrian sustained a suspected minor injury, and the driver was found at fault for failing to yield the right-of-way. The crash occurred in the morning under clear weather conditions, and the roadway surface was dry.

Figure 1 illustrates the crash location and direction of pedestrian and vehicle travel.

### **SCHOOL-SPECIFIC CONTEXT**

- School Type: Watkins Mill High School
- School Hours (Arrival / Dismissal): 8:05 a.m./ 2:50 p.m.
- School Enrollment: 1,577 (2024-2025 School Year)
- Crossing Guards Present (No): Crossing guard is not present at the intersection where the crash occurred

## **INFRASTRUCTURE & CONDITIONS**

## • Sidewalk Coverage

Continuous sidewalk coverage is present on both sides of Montgomery Village Avenue, as well as along Apple Ridge Road.

## • Crosswalk Visibility

Crosswalks are present at all approaches of the intersection

## • Lighting at Location

Present

### • Speed Limit / School Zone Limit:

The speed limit of Montgomery Village Avenue is 35mph, and speed limit on Apple Ridge Road is 25 mph.

## • Intersection Geometry:

The intersection of Montgomery Village Avenue and Apple Ridge Road is a signalized four (4) way intersection.

## • Transit Stop

The nearest bus stop is approximately **200 feet** from the intersection, along Apple Ridge Road. The bus stop IDs are **20046** and **28914**.

## **Nearby School Facilities (e.g., playgrounds, parking lots):**

North Creek Community Center and Pool are located approximately **550 feet** from the crash location.

Apple Ridge Ballfield is located on the northeast corner of the intersection of Apple Ridge Road and Montgomery Village Avenue.

### SITE OBSERVATIONS


- Observation Date/Time: 9am, October 10,2025
- Pedestrian Activity: We did not observe any pedestrian activity
- Vehicle Activity (☐ Low ☑ Moderate ☐ High):
- Drop-off / Pick-up Operations (☐ Organized ☐ Congested ☐ Observed Conflicts):
   N/A
- Visibility / Obstructions: None
- Driver Behavior: During time of the site visit, significant traffic was not observed at this location

# **CRASH HISTORY (At the location)**

Total Crashes (Last 10 Years): A total of **37 crashes** occurred over a period of nearly ten years, from 2015 to September 12, 2025. (*Note: 2025 data is partial.*)

Crash data distribution by year:





Crash data by severity and Involvement

Category	Count	Percent
Total Injury Crashes	21	56.8
Total Property Damage	16	43.2
Crashes		
Pedestrian Involved	4	10.8
Bicycle Involved	0	0
Scooter Involved	0	0

### **FINDINGS:**

No infrastructure deficiencies were identified at this location.

### **RECOMMENDATIONS (Select)**

- ☑Engineering Improvements (e.g., raised crosswalks, signals, bump-outs)
- Signage Enhancements (e.g., flashing beacons, school zone signs)
- $\square$  Lighting Upgrades (e.g., LED installations at crossings)
- $\square$  Education / Outreach (e.g., SRTS curriculum, parent letters)
- Enforcement / Crossing Guard (e.g., police presence, guard reassignment)
- Maintenance (e.g., repaint markings, remove foliage)
- □ Further Study Needed? (□ Yes ☑ No If yes, describe)

## **Engineering Improvement Recommendation**

The roadway medians in both directions should be extended to improve pedestrian safety and facilitate safer crossings. MCDOT is pursuing this median extension as part of the <u>Montgomery Village Avenue Safety Improvement project</u>.

### **Maintenance Recommendations**

The street should be scheduled for resurfacing. MCDOT has planned the resurfacing of Montgomery Village Avenue for **Spring 2026**.

#### **SITE PHOTOS / MAPS**

- ☑ Photos Attached
- ☐ School Walk Zone Map Included




Figure 1: Crash location and direction of pedestrian and vehicle travel




Figure 2: Crash Location Map