

## Fatal Crash Review

Location: Gridley Road at Selfridge Road

Accident Date: Friday, June 3, 2022

Accident Time: Approximately 10:00 PM

Local case number: 220023874

Review Date: June 22, 2022

Concurrence: Michael L. Paylor

Date: June 27, 2022

### Location and Site Description:

Gridley Road at Selfridge Road is an All-Way stop controlled intersection. Selfridge Road is a north-south oriented two-lane undivided (one lane each direction) primary residential roadway. Gridley Road is a east-west aligned two-lane undivided (one lane each direction) primary residential roadway, with the exception of the east leg which is it a three-lane undivided (one westbound and 2 eastbound) roadway. The posted speed limit on both roads is 25 mph. Marked ladder bar crosswalks exist on the east and south legs. There are two lighting fixtures on utility poles, one at the NE corner, the other on the south leg 70' south of Gridley Road..

### Description of Crash:

Preliminary investigations indicated vehicle was making a left turn from southbound Selfridge Road onto eastbound Gridley Road and struck the pedestrian in the crosswalk.

### Observations:

A field investigation was conducted at the crash location on June 21, 2022. All required signs and pavement markings at this intersection are in place and in good condition with the exception of the southern portion of the crosswalk on the east leg, which is partially faded. A check of the Montgomery County Streetlights website showed that the lighting fixtures are operational.

### Conclusion/Recommendation:

Refresh the ladder bar pavement markings on the east leg.

### Pictures:

See pages 2, 3 and 4.

Southbound Selfridge Road



Northbound Selfridge Road





Westbound Gridley Road



Eastbound Gridley Road





Faded Crosswalk – East Leg – Gridley Road

