



Lincoln HS

(P362302)

Category	General Government	Date Last Modified	01/12/22
SubCategory	County Offices and Other Improvements	Administering Agency	General Services
Planning Area	Rockville	Status	Ongoing

EXPENDITURE SCHEDULE (\$000s)

Cost Elements	Total	Thru FY22	Rem FY22	Total 6 Years	FY 23	FY 24	FY 25	FY 26	FY 27	FY 28	Beyond 6 Years
Planning, Design and Supervision	265	-	-	265	265	-	-	-	-	-	-
Construction	1,235	-	-	1,235	1,235	-	-	-	-	-	-
TOTAL EXPENDITURES	1,500	-	-	1,500	1,500	-	-	-	-	-	-

FUNDING SCHEDULE (\$000s)

Funding Source	Total	Thru FY22	Rem FY22	Total 6 Years	FY 23	FY 24	FY 25	FY 26	FY 27	FY 28	Beyond 6 Years
G.O. Bonds	1,500	-	-	1,500	1,500	-	-	-	-	-	-
TOTAL FUNDING SOURCES	1,500	-	-	1,500	1,500	-	-	-	-	-	-

APPROPRIATION AND EXPENDITURE DATA (\$000s)

Appropriation FY 24 Request	-	Year First Appropriation	FY23
Cumulative Appropriation	1,500	Last FY's Cost Estimate	1,500
Expenditure / Encumbrances	-		
Unencumbered Balance	1,500		

PROJECT DESCRIPTION

The former Lincoln High School is a landmark in Montgomery County's black education history. Opened in 1935, it is the oldest remaining high school building and the only junior high school constructed for black students in Montgomery County. The renovation includes roof replacement and some building envelope repair, in order to protect further deterioration of the building.

LOCATION

595 N Stonestreet Ave, Rockville, MD 20850.

ESTIMATED SCHEDULE

Work is expected to be completed in FY23.

PROJECT JUSTIFICATION

The former Lincoln High School, located in Rockville, is a landmark in Montgomery County's black education history. Opened in 1935, it is the oldest remaining high school building and the only junior high school constructed for black students in Montgomery County. The building was most recently occupied by Crusader Baptist Church of God. A structural and environmental assessment of the facility was performed in March 2020 by O'Connell and Lawrence at DGS's request and revealed a wide array of structural issues that indicated property maintenance code violations for the existing building that warranted timely abatement. The report indicated that a renovation would correct structural problems (the roof is in danger of severe failure), correct code violations (the plumbing, mechanical and electrical systems are noncompliant), and mitigate environmental issues by removing lead and asbestos. The report also stated that the structural and water damage cannot be fully determined without removal of the roof/ceiling assembly as well as plaster and drywall at the exterior load bearing walls and interior columns. In March 2020, the City of Rockville issued a notice that the facility should not be occupied in its current state

COORDINATION

City of Rockville