

Supplemental Materials Customized Reporting Tool for the Vision Zero Web Map



Submit a roadway hazard via a web browser




A smartphone App – reporting hazards for pedestrians



Gallery



Report a vehicle running red lights or stop signs via a smartphone



Edited 21 hours ago



Submitted


Gallery

Status




Report pedestrian "Long Wait to Cross" via a smartphone

PDF Reporting for DOT engineers and managers



DOT manager or engineer reviews a report submitted by the public

Montgomery County, Maryland



PDF Report generation widget

The following 3 PDF reports were generated by the REPORTLAB PDF Report generation widget:



DTS GIS Vision Zero Report



Problem Observed #5 Long Wait to Cross

Location:	379 Hungerford Dr Rockville, MD 20850
Issue reported during:	Walking
Problem observed:	Long Wait to Cross
Additional details:	Since there are lots of cars on the other side of Beall Ave. And very short distance for them to wait, the wait for cross is too long
When did the problem occur:	1551277388267
Number of Votes:	None
Public View:	Yes
Name:	Varun
Phone:	12406143638
Email:	Varungisp@gmail.com
Status:	Submitted
Assigned To:	None
Resolution:	None
Creation Date:	02-27-2019 09:27 AM
Edit Date:	02-27-2019 09:50 AM
Editor:	varungisp7

Attachments:









Montgomery County, Maryland



DTS GIS Vision Zero Report



Problem Observed #3 Long Wait to Cross

Location:	98-2 Beall Ave Rockville, MD 20850	
Issue reported during:	Walking	
Problem observed:	Long Wait to Cross	
Additional details:	Very long wait to cross the road	
When did the problem occur:	1551129525023	
Number of Votes:	None	
Public View:	Yes	
Name:	Varun	
Phone:	5712125834	
Email:	Varungisp@gmail.vom	
Status:	Completed	
Assigned To:	None	
Resolution:	None	
Creation Date:	02-25-2019 16:44 PM	
Edit Date:	02-27-2019 09:51 AM	
Editor:	varungisp7	

Attachments:





DTS GIS Vision Zero Report



02-26-2019 14:22 PM Report For Problem Observed = 'ALL'

Problem Observed #1 Blocking Bicycle Lane

Location:	21 Maryland Ave, Rockville, Maryland, 20850	
Issue reported during:	Biking	
Problem observed:	Blocking Bicycle Lane	
Additional details:	Bike lane damaged	
When did the problem occur:	1550962236705	
Number of Votes:	None	
Public View:	Yes	
Name:	Varun	
Phone:	5712125834	
Email:	varungisp@gmail.com	
Status:	Submitted	
Assigned To:	None	
Resolution:	None	
Creation Date:	02-23-2019 17:48 PM	
Edit Date:	02-24-2019 10:54 AM	
Editor:	varungisp7	

Attachments:

