Resurfacing: Fire Stations (P458429)

Category Sub Category Administering Agency Planning Area	Public Safety Fire/Rescue Ser General Service Countywide	Date Last Modified Required Adequate Public Facility Relocation Impact Status					11/17/14 No None Ongoing					
		Total	Thru FY15	Est FY16	Total 6 Years	FY 17	FY 18	FY 19	FY 20	FY 21	FY 22	Beyond 6 Yrs
EXPENDITURE SCHEDULE (\$000s)												
Planning, Design and Supervision		672	62	106	504	84	84	84	84	84	84	0
Land		0	0	0	0	0	0	0	0	0	0	0
Site Improvements and Utilities		0	0	0	0	0	0	0	0	0	0	0
Construction		1,957	0	661	1,296	216	216	216	216	216	216	0
Other		0	0	0	0	0	0	0	0	0	0	0
	Total	2,629	62	767	1,800	300	300	300	300	300	300	0
				FUNDIN	G SCHEDU	LE (\$000s)						
G.O. Bonds		2,629	62	767	1,800	300	300	300	300	300	300	0
	Total	2,629	62	767	1,800	300	300	300	300	300	300	0

APPROPRIATION AND EXPENDITURE DATA (000s)

Appropriation Request	FY 17	300
Appropriation Request Est.	FY 18	300
Supplemental Appropriation Requ	0	
Transfer	0	
Cumulative Appropriation		829
Expenditure / Encumbrances	242	
Unencumbered Balance	587	

Date First Appropriation	FY 84	
First Cost Estimate		
Current Scope	FY 17	2,629
Last FY's Cost Estimate	2,749	
Partial Closeout Thru		6,484
New Partial Closeout		62
Total Partial Closeout	6,546	

Description

This project provides for the repair and replacement of paved surfaces at fire and rescue stations where existing paved surfaces are in poor and deteriorating condition.

Estimated Schedule

Scheduling is determined through annual inspections performed by the Department of General Services, Division of Building Design and Construction, in consultation with the Montgomery County Fire and Rescue Service. The station schedule displays anticipated priorities only and may be amended, if required, due to fire station pavement safety considerations.

Cost Change

The increase is due to the addition of funding in FY21 and FY22, partially offset by capitalizing prior year expenditures.

Justification

The current candidate project list was determined by a survey conducted by the Department of General Services, Division of Building Design and Construction. The ongoing project need for exterior resurfacing at fire and rescue stations is due to the continuous use by heavy equipment such as pumpers and ladder trucks. While surfaces at some stations have lasted many years, others have deteriorated and failed in less than seven years.

Fiscal Note

Debt service for this project will be financed with Consolidated Fire Tax District Funds.

Disclosures

Expenditures will continue indefinitely.

Coordination

Montgomery County Fire and Rescue Service, Local Volunteer Fire and Rescue Departments, Department of General Services