

CategoryMontgomery County Public SchoolsDate Last Modified07/06/16SubCategoryCountywideAdministering AgencyPublic SchoolsPlanning AreaCountywideStatusOngoing

EXPENDITURE SCHEDULE (\$000s)

Cost Elements	Total	Thru FY18	Rem FY18	Total 6 Years	FY 19	FY 20	FY 21	FY 22	FY 23	FY 24	Beyond 6 Years
Planning, Design and Supervision	615	615	-	-	-	-	-	-	-	-	-
Construction	5,785	5,785	-	-	-	-	-	-	-	-	-
TOTAL EXPENDITURES	6,400	6,400	-	-	-	-	-	-	-	-	-

FUNDING SCHEDULE (\$000s)

Funding Source	Total	Thru FY18	Rem FY18	Total 6 Years	FY 19	FY 20	FY 21	FY 22	FY 23	FY 24	Beyond 6 Years
G.O. Bonds	6,400	6,400	-	-	-	-	-	-	-	-	-
TOTAL FUNDING SOURCES	6,400	6,400	-	-	-	-	-	-	-	-	-

APPROPRIATION AND EXPENDITURE DATA (\$000s)

Appropriation FY 20 Approp. Request	-	Year First Appropriation	FY12
Cumulative Appropriation	6,400	Last FY's Cost Estimate	6,400
Expenditure / Encumbrances	-		
Unencumbered Balance	6,400		

PROJECT DESCRIPTION

MCPS operates cafeterias in schools throughout the county to provide breakfast and lunch to thousands of students each day. Because of these food service functions, each MCPS school is considered a food establishment. Under a 2005 U.S. Department of Justice Consent Decree between WSSC, US EPA, and MDE to enforce the Clean Water Act, WSSC was required to develop a new fats, oils, and grease (FOG) program that requires all food establishments be inspected and comply with FOG regulations to receive FOG permits. WSSC has modified its plumbing code and heighten inspections and enforcement of the FOG regulations as part of its responsibility under the Consent Decree. It has a dedicated unit to enforce the FOG regulations and will issue Notice of Violations for facilities that are lacking the plumbing system components required under the revised WSSC code. WSSC is in its first year of inspections of MCPS facilities and, therefore, the list of schools that will need upgrades to the existing grease removal devices is not complete. An FY 2012 appropriation and amendment to the FY 2011-2016 CIP was approved to address WSSC FOG Notice of Violations including the installation of grease interceptors and associated plumbing devices. An FY 2013 appropriation was approved to begin the remediation process of MCPS facilities where existing grease removal devices must be upgraded to meet WSSC requirements.

WSSC Compliance 50-1

COORDINATION

WSSC Permits

WSSC Compliance 50-2