





# 1. Repair concrete parapets






## 2. Repair prestressed concrete beams





### 3. Repair concrete buttress backwalls



Scope of Work
Display C-1







4. Replace bridge deck compression joints





5. Replace existing street lighting with in-kind concrete poles on bridge, fiberglass poles off bridge and LED light fixtures





**SCOPE OF WORK**Display C-2







6. Seal cracks on concrete deck wearing surface



7. Repair approach concrete sidewalk at both ends of the bridge











8. Install new drainage troughs on both side of buttress nos. 11, 13, 15, 17, 19, 21, 23, 25 under deck expansion joints
















- 9. Improve storm drainage at approach on Howard County side
- 10. Resurface/repave asphalt approach roadway on Howard County side





Scope of Work

Display C-5










11. Construct a permanent turnaround site with asphalt pavement at the existing tanker fire truck water refill site on the Howard County side for police vehicles, fire and rescue trucks, and school buses of **Montgomery County** and Howard County

Scope of Work









12. Relocate the existing diagonal crosswalk over **Brighton Dam Road and** associated walkway connection for Brighton **Dam Azalea Garden on** the Montgomery County side, and install two additional streetlights for the crosswalk

Scope of Work
Display C-7