

Subject: FW: Kensington Road abandonment
Date: Wednesday, February 5, 2020 at 8:38:25 AM Eastern Standard Time
From: Panjshiri, Atiq
To: McCray, Tiara
CC: Terry, Mark, Torma, Rebecca, Pallas, Edward, LaBaw, Marie, Hanley, Kyle K., Funderburk, Kim C.
Category: Important / Action Item
Attachments: image001.jpg, image003.jpg, image005.jpg

Good Morning Tiara:

We DO NOT recommend abandonment of Kensington Blvd. There are two parallel Storm Drain as well as water and Sewer main within the Right of way (see the GIS map below).

Atiq Panjshiri

Manager, Right of Way Plan Review
Division of Land Development, MCDPS
Montgomery County, Maryland
255 Rockville Pike, 2nd Floor
Rockville, Maryland 20850
Tel: 240-777-6352
email: Atiq.Panjshiri@montgomerycountymd.gov

Have you tried DPS eServices?


<http://permittingservices.montgomerycountymd.gov/DPS/eservices/AboutServices.aspx>

This message (including any attachments) may contain confidential information intended for a specific individual and purpose, and is protected by law. If you are not the intended recipient, you should delete this message. Any disclosure, copying, or distribution of this message, or the taking of any action based on it, is strictly prohibited.

From: Jeeves, Brian <Brian.Jeeves@montgomerycountymd.gov>
Sent: Wednesday, February 5, 2020 8:32 AM
To: Panjshiri, Atiq <Atiq.Panjshiri@montgomerycountymd.gov>
Subject: Kensington Road abandonment

Atiq,

Here is a snip of our GIS map of the area showing to 2 storm drain lines and water and sewer lines



This is just the storm drain lines





Here is the color image



Brian Jeeves

Senior Permitting Services Specialist
 Department of Permitting Services
 Right of Way Plan Review Section
 255 Rockville Pike, 2nd Fl
 Rockville, MD 20850
 Office 240-777-6284; Fax 240-777-6339
 email Brian.Jeeves@montgomerycountymd.gov