Stream Conditions

Montgomery County, Maryland

2011 - 2015

- Excellent
- Good
- Fair
- Poor
- No Data Available

Stream Monitoring Sites

- Baseline Cycle Site
- Targeted or Historical Site

Station Type

- Restoration Monitoring
- SPA Monitoring
- Special Protection Area (SPA)

- WATERSHEDS
- Subwatersheds
- Urban Centers and Municipalities

N

Lower Monocacy

Upper Potomac Direct

Seneca Creek

Lower Potomac Direct

Patuxent

Rock Creek

Anacostia

Cabin John

I love clean water!

DEPARTMENT OF
ENVIRONMENTAL PROTECTION
MONTGOMERY COUNTY • MARYLAND