

RIFFLE GRADE CONTROL (RGC)

SOIL LIFT (SL)

Before




After



Before




After



Grosvenor Site GL 10 Stream Restoration Project



Stream Restoration Techniques



Legend

- | | |
|------------------------------|------------------------------|
| Proposed 1-ft Contour | Existing 2-ft Contour |
| Contour | Contour |
| Index Contour | Index Contour |
| Tree | Limit of Disturbance |
| Tree Removed | Temporary Access Road |
| Tree Removed (d > 24") | Property Boundary |
| Rock Structure | |
| Riffle Grade Control | |
| Soil Lift | |

CROSS VANE (CV)



Before



After



IMBRICATED ROCK WALL (IR)