

CROSS VANE (CV)



Before



After

J-HOOK (JH)



Before




After



# Grosvenor Site GL 06 Stream Restoration Project


## Stream Restoration Techniques



### Legend

- |                        |                       |
|------------------------|-----------------------|
| Proposed 1-ft Contour  | Existing 2-ft Contour |
| Contour Index Contour  | Contour Index Contour |
| Tree                   | Limit of Disturbance  |
| Tree Removed           | Temporary Access Road |
| Tree Removed (d > 24") | Property Boundary     |
| Rock Structure         |                       |

**ROCK SILL (RS)**  
**OUTFALL PROTECTION (OP)**



Before



After

STEP POOL (SP)