


DICKERSON SO2 MONITORING

- Three monitoring stations installed by JJ Wilbur company the week of April 23, 2018
- Stations operations observed for the next week with some minor adjustments
- All stations considered operational May 1, 2018
- May 18th – minor adjustment made to each site to adjust zero (background) reading
- May 24-June 1 each site was formally audited by the Maryland Department of the Environment
- All sites passed with no issues
- Each site is checked by an independent contractor twice a month.
- QA/QC procedure developed TRC is being followed

May 2018 SO2 values (ppb) Station 1



May 2018 SO2 values (ppb) Station 2

25

20

15

10

5

0


-5

EPA 1 Hour Standard = 75 ppb



01/05/2018 00:00
02/05/2018 00:00
03/05/2018 00:00
04/05/2018 00:00
05/05/2018 00:00
06/05/2018 00:00
07/05/2018 00:00
08/05/2018 00:00
09/05/2018 00:00
10/05/2018 00:00
11/05/2018 00:00
12/05/2018 00:00
13/05/2018 00:00
14/05/2018 00:00
15/05/2018 00:00
16/05/2018 00:00
17/05/2018 00:00
18/05/2018 00:00
19/05/2018 00:00
20/05/2018 00:00
21/05/2018 00:00
22/05/2018 00:00
23/05/2018 00:00
24/05/2018 00:00
25/05/2018 00:00
26/05/2018 00:00
27/05/2018 00:00
28/05/2018 00:00
29/05/2018 00:00
30/05/2018 00:00
31/05/2018 00:00
01/06/2018 00:00

May 2018 SO2 values (ppb) Station 3







Potomac River

MARYLAND
VIRGINIA
Potomac River

28

Dickerson Rd

Dickerson

28

28

Montgomery County
Compost Facility

Dickerson
Conservation
Park

Darnestown Rd

28

3

1

2